Crowcon Technical Note

|	
Document Reference:	**GEN117**
Document applies to:	**C02136/AMBER & C02136/RED**
Release Date:	**31st May 2024**
Subject:	**Sonos Klaxon Sounder Beacons (Issue 2)**

Between June 2023 and Feb 2024, Sonos made a change to the functionality of their Klaxon Sounder/Beacon. The sounder and beacon have been linked internally, meaning that that the sounder was no longer mutable on its own, leaving the beacon still flashing.

Because this functionality is closer to how Fire Alarm systems operate, Crowcon have reverted to the original design, which is more in line with the Gas Detection Industry.

The two versions look almost identical. The only way to confirm which model you have is to check the Part Number printed on the inside of the device.

Incorrect (not for Gas Detection)
Crowcon Part Number:
C02136/AMBER - PSC-0042
C02137/RED - PSC-0049

Correct (for Gas Detection)
Crowcon Part Number:
C02136/AMBER - PSC-0027
C02137/RED – PSC-0013

The "PSC" Number can be found in this area

If you have the incorrect part and this does not suit your application please contact Crowcon for a replacement.

_____

For more information, please contact +44 (0)1235 557700, technicalsupport@crowcon.com

Crowcon Detection Instruments Ltd

172 Brook Drive, Milton Park, Abingdon, Oxfordshire, OX14 4SD,
UK Tel: +44 (0) 1235 557700 Fax: +44 (0) 1235 557749
Email: technicalsupport@crowcon.com

Page **1** of **1**

Company registered no. 00978878

A **Halma** company