

## **Technical Note**

February 2012

## HCl Sensor Portable GEN028

Product: Tetra, Tetra 3 and Gasman

Subject: HCI Sensor

In October 2008, due to unacceptable instability with the HCl (hydrogen chloride) sensor used in Crowcon's Gasman, T3 and Tetra units, the sensor was withdrawn from sale.

Its reliability was not acceptable to remain within the range. Due to this issue, any instruments above that are in use and containing this HCl sensor are no longer able to be serviced or repaired.

However, Crowcon are able to offer the detection of HCI in Triple Plus+ and Detective+ units for customers who want to continue detecting.

Teresa Curran Junior Product Manager